



CPI PRODUCT BULLETINS FOR MEDICAL X-RAY DEVICES

CB10Indico146	ADR Tank Recall
SB09CMP145	Inverter Shield Upgrade
PB09GEN144	CPI Product Improvement: DSS Configuration and Compatibility Revisions
SB09Indico143	Indico 100 RAD X-ray Generator: User Tubes Error
PB09Indico142	Redesigned Console Board for 31 x 42 cm R&F Membrane Consoles
CB09CMP141	Corrective Action Bulletin: CMP200 Intermittent Low kV & mA Errors and/or Filament Errors
PB09GEN140	CPI Product Improvement – GenWare® MP
PB09GEN139	CPI Product Improvement – Console CPU Board
CB09CMP138	CPI Product Improvement – HT Spun Aluminum Tank (Amended January 2010)
SB09GEN137	CPI-Canon DR Interface: Possible Loss of Software Synchronization
CB09CMP136	Ground Leakage Current: Single-Phase CMP 200 DR
CB09CMP135	CMP200 Software Update for Units with a Mini Console
CB07CMP134	CMP200 DR HV Auxiliary Board F2 and F3 Value
CB09CMP133	CMP200 Fan Cover Installation
PB08CMP132	CMP200 Power Supply Upgrade
CB08GEN131	Software Upgrade for CPI – Canon DR Interface
PB08GEN130	CANCELLED – Replaced with CB08GEN131

This page will be updated and changed as new Bulletins are released. Previously released Bulletins are available by submitting the request form asking for a listing of older Bulletins.