



CPI PRODUCT BULLETINS FOR MEDICAL X-RAY DEVICES

CB11RV156	CPI RAD VISION: Discontinued Study Addition
SB11RV155	CPI RAD VISION Software Release Notes (2.2.1.1.)
PB10Indico154	Indico Generator CPU Board with Innovasic Microprocessor
SB10RV153	CPI RAD VISION Software Release Notes (1.8.1.104)
SB10RV151	CPI RAD VISION Software Release Notes (1.8.1.103)
CB10Indico150	Indico 100 CPU Board Loss of Calibration Data
CB10CMP149	CMP200 Generator kW limit reached at unusually low kV
CB10CMP148	CMP200 DR Potential Dual Speed Starter Wiring Error
SB10CMP147	CMP200 Revised Auxiliary Transformer and Revised F10 on HV Auxiliary Board
CB10Indico146	ADR Tank Recall
SB09CMP145	Inverter Shield Upgrade
PB09GEN144	CPI Product Improvement: DSS Configuration and Compatibility Revisions
SB09Indico143	Indico 100 RAD X-ray Generator: User Tubes Error
PB09Indico142	Redesigned Console Board for 31 x 42 cm R&F Membrane Consoles
CB09CMP141	Corrective Action Bulletin: CMP200 Intermittent Low kV & mA Errors and/or Filament Errors
PB09GEN140	CPI Product Improvement – GenWare [®] MP
PB09GEN139	CPI Product Improvement – Console CPU Board
CB09CMP138	CPI Product Improvement – HT Spun Aluminum Tank (Amended January 2010)

This page will be updated and changed as new Bulletins are released. Previously released Bulletins are available by submitting the request form asking for a listing of older Bulletins.